

Laboratory Phantom




Fig. E-1

The bar graphs represent the percentage of error for each of the three ranges of true wear simulated with the laboratory phantom apparatus.

Clinical Radiographs




Fig. E-2

The bar graphs represent the percentage of error with clinical radiographs, categorized into the three ranges of true wear as measured directly from the liners.